

$\frac{1}{3}$

Type 1 Facility Closeout Report

Section A. Facility Data

Facility No.	B519
Facility Descriptor:	Storage Building, 1020 sqft.
Project:	RISS Area 1
Date of Demolition:	5/13/2003
Additional Information:	Steel Frame Structure with Transite panel sides and roof.
<i>(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)</i>	

Section B. Final Characterization Data

Reconnaissance Level Characterization Report <i>(concurrence received)</i>	Reconnaissance Level Characterization Report Concurrence- Steven Gunderson to Richard DiSalvo, dated February 23, 2003
In-process Characterization	NA
Pre-Demolition Survey Report <i>(approval received)</i>	NA
Post-Demolition Survey Report <i>(as necessary)</i>	NA

Section C. Waste Data *(complete categories as appropriate)*

Sanitary Disposal

Disposal Site:	BFI Tower Road, Commerce City, CO
Waste Volume (yd ³):	20
Waste Weight (tons):	3.38
Additional Information:	

Hazardous Disposal

Disposal Site:	N/A
Waste Volume (m ³):	
Additional Information:	

TSCA Waste Disposal

Disposal Site:	NA
Waste Volume (m ³):	
Additional Information:	

Asbestos Waste Disposal

Disposal Site:	Non-Friable Only BFI Tower Road, Commerce City, CO
Waste Volume (yd ³):	30
Waste Weight (tons):	6.15
Additional Information:	

Low-Level Waste Disposal

Disposal Site:	NA
Waste Volume (m ³):	
Additional Information:	

Low-Level Mixed Waste Disposal

Disposal Site:	
Waste Volume (m ³):	
Additional Information:	

Recycled Material

Recycle Facility:	NA
Waste Volume (m ³):	
Additional Information:	

Property Disposition

Receiver Locations <i>(major items only)</i> :	NA
Volume (m ³):	
Weight (tons):	
Additional Information:	


Type 1 Facility Closeout Report

Section D. Approvals

Kaiser-Hill Project Manager

Name/Signature

CJ Freeman



Date

05/21/05

Instructions for Completion of Type 1 Facility Closeout Report

Additional Facility Information

B519 was a 1020 square foot Alarm Maintenance building constructed in the mid-1970's. The facility had a frame structure with Transite walls and ceilings.

Recently, the building was used to store spare parts and equipment for the Alarms Maintenance Group. Prior to that, in the mid-1970's the building was used as a storage building for the B771 Maintenance Department.

The building had temporary power in the early 1990's, but that was subsequently removed. No other utilities were associated with this facility.

The slab of the facility remained after demolition of the superstructure for removal by ER. The slab was subsequently removed and disposed of.

There were no known spills in the facility, the facility was never used for RCRA waste storage, and is not associated with any known IHSS, PAC, or UBC.

Building 519 Location Map

Standard Map Features

- Demolished Facility
- Remaining Facility
- Leases and Ponds
- Diminished Roads
- Paved Roads
- Old Roads
- Railroad Removed
- Railroad Remaining
- Fence Remaining
- Streams, Ditches, or Other Drainage Features

N

Scale: Feet
0 20 40 60 80
State Plane Coordinate Projection
Colorado Central Zone (3478)
Datum: NAD27

U.S. Department of Energy
Rocky Flats Environmental Technology Site

Prepared By:

CH2M HILL

GIS DEPT. (303) 968-7707

Prepared For:



DATE: 5/24/2005

